



Fully Inflated

Circuit is way too strong resulting in an ALP that inflated well before its manufactured timeframe. It is possible to still have bait inside as well but cannot squeeze any more bait out due to swollen appearance.



Partially Inflated

This ensures fresh bait has been continuously oozing out of the ALP at its intended rate so at 60% of its intended lifespan, it should only be 60% inflated. Notice how I cant squeeze it all the way down? That's what we want.



Did Not Inflate (DNI)

Able to be completely crushed, second chamber not inflated or barely inflated at all. Circuit unable to complete or seal broken. It is possible to have no bait and still consider DNI, rarely does this happen but it is possible.